

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

**2009 Hummer H3 4WD I-5 4D SUV Base 3.7L**

<b>VIN</b>	5GTEN13E298146153		
<b>Ext. Color</b>	Black		
<b>Int. Color</b>	Black	<b>Interior</b>	Cloth
<b>Mileage</b>	71,578 <b>Actual Miles</b>		
<b>Engine</b>	3.7L 5-Cylinder Gas		
<b>Transmission</b>	Automatic		



## Auction Data

<b>Sale Date</b>	To Be Announced		
<b>Run #</b>	To Be Announced	<b>Inv #</b>	3046
<b>Consignor</b>	GSA FLEET SERVICES		

## Declarations

<b>Warranty</b>	GSA Regular Terms
<b>Mileage</b>	71,578 <b>Actual Miles</b>
<b>Title</b>	Clear Title

## Equipment

- 4 Wheel Drive
- Air Conditioning
- Trip Counter
- Alloy Wheels
- Rear Wiper
- Electric Mirrors
- Automatic Transmission
- Electronic Traction Control
- Dual and Side Air Bags
- Tilt Steering Wheel
- Rear Defog
- 5 Cylinder Gas
- Power Windows
- Cruise Control
- AM/FM CD
- Power Steering
- 5 Passenger
- Power Locks
- Anti Lock Brakes
- Hard Top
- Power Brakes

## Damage Descriptions (CR completed on 2/16/2015 by SKYLAR FICKLIN)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

### Front

1	Hood	Chips	Multiple Instances						--
									--

### Front Subtotal

--	--	--	--	--	--

### Interior

2	Carpets	Dirty	Multiple Instances						--
									--

# 2009 Hummer H3 4WD I-5 4D SUV Base 3.7L

VIN: 5GTEN13E298146153

Inv#: 3046

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
3	Headlining	Dirty	Multiple Instances						--
4	Interior	Dirty	Multiple Instances						--
5	Seats	Dirty	Multiple Instances						--

## Interior Subtotal

--	--	--	--	--	--
		--	--	--	--

## Left

6	Left Front Fender	Scratched	Multiple Instances						--
7	Left Rear Door	Scratched	Multiple Instances						--

## Left Subtotal

--	--	--	--	--	--
		--	--	--	--

## Mechanical

8	Engine	Checked - Ok	None						--
9	Odometer	Checked - Ok	None						--
10	Transfer Case 4x4	Checked - Ok	None						--
11	Transmission	Checked - Ok	None						--

## Mechanical Subtotal

--	--	--	--	--	--
		--	--	--	--

## Right

12	Right Front Fender	Scratched	Multiple Instances						--
----	--------------------	-----------	--------------------	--	--	--	--	--	----

## Right Subtotal

--	--	--	--	--	--
		--	--	--	--

## Structural

13	Frame	Checked - Ok	None						--
----	-------	--------------	------	--	--	--	--	--	----

## Structural Subtotal

--	--	--	--	--	--
		--	--	--	--

## 2009 Hummer H3 4WD I-5 4D SUV Base 3.7L

VIN: 5GTEN13E298146153

Inv#: 3046

Total

--	--	--	--	--	--
		--	--	--	--

### Tires

Region	Brand	Size	Tread Depth
Left Front	MASTERCRAFT	/-	Average (Average)
Left Rear	MASTERCRAFT	/-	Average (Average)
Right Front	MASTERCRAFT	/-	Average (Average)
Right Rear	MASTERCRAFT	/-	Average (Average)
Spare	FACTORY	/-	Average (Average)

### Miscellaneous

Coolant level	OK
Interior odor	OK
Oil level	OK
Transmission fluid level	OK

### Images



## 2009 Hummer H3 4WD I-5 4D SUV Base 3.7L

VIN: 5GTEN13E298146153

Inv#: 3046

